**Version Info**

**Firmware for SX3206HPP(UN) 1.20. This firmware is fully adapted to Omada Controller V5.15.24.**

Enhancements

1. Optimize the dot1x authentication function.

Bug fixed

1. Fixed the issue of spanning tree anomalies in special scenarios.