Release Note for ER706W-4G(JP) v2.20

Important Notice:

No.

Version Info:

1. Applied Models:

    a) ER706W-4G(JP) v2.20

2. Firmware Version: 2.1.3 Build 20251031 Rel.56968

3. Minimum FW Version for Update:

    a) JP v2.20: 2.1.2 Build 20250822 Rel.22554

For downloading of any firmware version, please refer to Omada Download Center.

4. Recommended Controller Version: Custom Version 5.15.21.60 (Omada Cloud Essentials and Omada Cloud-Based Controller Not Supported)

5. Recommended APP Version: No

New Features:

No.

Enhancements:

No.

Bug Fixed:

Fixed the issue that VLAN was lost when selecting MAP-E/DS-Lite dial-up method during Quick Setup.

Additional Information:

The default LAN subnet has been changed to 192.168.0.0/24.