Bug fixed

1. Fix the issue of IP loss caused by repeated modification of VLAN configuration by the controller.

2. Fix httpJson memory leak issue