Bug fixed:

1. Fixed an issue where client association failed when connecting to an SSID configured with PPSK with RADIUS unbound MAC and mandatory PMF.
2. Fixed an issue where enabling a new entry in IoT Transport Streams might result in a configuration failure.
3. Fixed an issue where the logs could not be received by the syslog server after configuring VLAN.
4. Fixed an issue where the device could occasionally reboot unexpectedly.

Notes:

1. This version of firmware is applied to the Omada APP v4.25 or above.