Version Info

Firmware for ES205GP(UN) 1.20 and 1.26. Recommended Omada Controller V6.0.0.

Bug fixed

1. Fixed an issue where a PoE port could fail to supply power after a PoE reboot.