Version Info

Firmware for SL2428P(UN) 6.30 and 6.36. Recommended Omada Controller V6.0.0.

Bug fixed

1. Fixed HTTP JSON memory leak issue.

2. Fixed web reset failure issue.