Bug fixed

1. Fixed the issue of IP loss caused by repeated modification of VLAN configuration by the controller.

2. Fixed HTTP JSON memory leak issue.

3. Fixed web reset failure issue.