New Features

Removed support for the ECSP v1 protocol. Adoption using older Controller versions is no longer supported to prevent potential security vulnerabilities.

Enhancements

Improved the stability of the SNMP functionality.

Bug Fixes

Fixed a field-reported issue where a memory leak occurred when using the SNMP feature.

Fixed security vulnerabilities related to the connection with the Controller.

Others

None