Version Info:

1. Minimum FW Version for Update: 1.1.2 Build 20251013 Rel. 32717.

2. After upgrading to this version, it is not possible to roll back to FW versions earlier than 1.1.2. Contact Omada technical support if downgrade is required.

3. Recommended Omada Controller version 5.15 or above.

4. For downloading of any firmware version, please refer to Omada Download Center.

Bug fixed:

1. Fixed an issue where mandatory PMF could cause client association failures when using PPSK with RADIUS unbound MAC.

2. Fixed an issue where the syslog server could not receive logs after VLAN was configured.

3. Fixed an issue where the portal authentication process might fail.

4. Fixed an issue where the configuration failed to be delivered to the device after creating a new entry in IoT Transport Streams.

5. Fixed an issue where the device might experience a memory leak under certain circumstances.

Notes:

1. This version of firmware is applied to the Omada APP 4.24 or above.