Release Note

Important Notice:

This firmware upgrade is irreversible. Contact support if issues are encountered after the firmware upgrade.

Version Info:

1. **Firmware Version:** 2.0.4 Build 20260803 Rel.13055
2. **Applied Model:**

   ER605W(AU) v2.0
3. **Minimum FW Version for Update**:

   2.0.3 Build 20250717 Rel.72101
4. **Recommended Omada Controller version:** 6.2.14.
5. **Recommended Omada App version:** 5.3.
6. For downloading any firmware version, please refer to Omada Download Center .

Bug Fixed

1. Fix some security issues and enhance the security of the equipment.