

Release Note

Version Info:

1. **Firmware Version:** 1.4.1 Build 20260826 Rel. 14968
2. **Applied Model:** EAP773 v1.0
3. **Minimum FW Version for Update:** 1.1.2 Build 20251030 Rel. 58575
4. **Fully Adapted Omada Controller version:** 6.2.
5. **Fully Adapted Omada App version:** 5.2.
6. For downloading any firmware version, please refer to [Omada Download Center](#). For more information about firmware version number and fully adapted controller version, please refer to [Announcement on the Change of Omada Product Firmware Version Numbers](#).

New Features:

1. Added support for batch configuration via the Omada Config tool.
2. Added support for performing Portal authentication/deauthentication for clients from the client list on the web UI.
3. Added support for iperf3 throughput testing in the CLI system.
4. Added support for load balancing.
5. Added support for 6 GHz PPSK.
6. Added support for configuring time windows for Adaptive WLAN Optimization.
7. Added support for Wi-Fi Calling.
8. Added support for NAT Traversal.

Enhancements:

1. Optimized overall system stability.
2. Optimized cloud upgrade behavior during timeouts by supporting breakpoint resume.
3. Optimized the client list display on the web UI by adding a guest client list.
4. Optimized Band Steering to apply only at the SSID level.

Bug Fixed:

1. Fixed an issue where abnormal 2.4 GHz EAPOL frames could cause the device to reboot.