

Release Note

Version Info:

1. **Firmware Version:** 1.4.1 Build 20260826 Rel. 14968
2. **Applied Model:** EAP773 v1.0/v1.6
3. **Minimum FW Version for Update:** 1.1.2 Build 20251030 Rel. 58575
4. **Fully Adapted Omada Controller version:** 6.2.0.
5. **Fully Adapted Omada App version:** 5.2.
6. For downloading any firmware version, please refer to [Omada Download Center](#). For more information about firmware version number and fully adapted controller version, please refer to [Announcement on the Change of Omada Product Firmware Version Numbers](#).

New Features:

1. Added support for Omada Config, enabling batch device configuration via the Omada Config tool.
2. Added support for Portal authentication and de-authentication buttons in the Web UI client list.
3. Added support for iPerf3 throughput testing via CLI commands.
4. Added support for load balancing.
5. Added support for 6 GHz PPSK.
6. Added support for configuring a time window for Adaptive WLAN Optimization.
7. Added support for Wi-Fi Calling.
8. Added support for NAT Traversal.

Enhancements:

1. Optimized cloud firmware upgrade timeout handling, adding support for breakpoint resume (resumable downloads).
2. Optimized system stability.
3. Optimized the client list display in the Web management UI, adding a Guest Client List.
4. Optimized Band Steering behavior so it only takes effect at the SSID level.

Bug Fixed:

1. Fixed an issue where abnormal 2.4 GHz EAPOL frames could cause the device to reboot.