

Release Note

Version Info:

1. **Firmware Version:** 1.0.5 Build 20260814 Rel. 07240
2. **Applied Model:** EAP773 v2.0
3. **Minimum FW Version for Update:** 1.0.3 Build 20260325 Rel. 12642
4. **Fully Adapted Omada Controller version:** 5.15.24.
5. **Fully Adapted Omada App version:** 5.0.
6. For downloading any firmware version, please refer to [Omada Download Center](#). For more information about firmware version number and fully adapted controller version, please refer to [Announcement on the Change of Omada Product Firmware Version Numbers](#).

Enhancements:

1. Optimized overall system stability.

Bug Fixed:

1. Fixed an issue where, after changing the device fallback IP, the device web UI could intermittently become inaccessible.
2. Fixed an issue where Portal logout would fail when the logout domain contained uppercase letters, preventing logout via browser URL access.
3. Fixed an issue where the mDNS feature could intermittently stop working under specific configurations.
4. Fixed an issue where the device would not respond to IPv6 ping under specific configurations.