

Release Note

Version Info:

1. **Firmware Version:** 4.0.1 Build 20260920 Rel.32353
2. **Applied Model:**
 - a) Fusion Pro 2.5G PoE(UN) 1.0
 - b) Fusion Pro 2.5G PoE(UN) 1.6
3. **Minimum FW Version for Update:**
4.0.0 Build 20260914 Rel.73217
4. **Built-in Application version:**
 - a) Network: 6.3.20.1
 - b) Guard: 2.3.1
5. **Recommended Omada App version:**
 - a) Android: 5.3.54
 - b) iOS: 5.3.14
6. **Recommended Guard App version:**
 - a) Android: 1.2.13
 - b) iOS: 1.2.3
7. **Recommended Navi App version:** 1.7.
8. For downloading any firmware version, please refer to [Omada Download Center](#).

Bug Fixed

1. Fixed an issue where the Bluetooth App Setup would occasionally time out and fail to connect upon startup.
2. Fixed an issue where batch firmware upgrades for IPCs would fail.