

Release Note

Version Info:

1. **Firmware Version:** 1.0.40 Build 20260918 Rel. 22682
2. **Applied Model:**
 - a) Fusion 2.5G(UN) v1.0
 - b) Fusion 2.5G(UN) v1.6
3. **Minimum FW Version for Update:** 1.0.20 Build 20260425 Rel. 32539
4. **Built-in Omada Controller version:** 6.3.14.
5. **Recommended Omada App version:**
 - a) Android: 5.2.30
 - b) iOS: 5.2.18
6. For downloading any firmware version, please refer to [Omada Download Center](#).

Bug Fixed

1. Fixed an issue where the Bluetooth App Setup would occasionally time out and fail to connect upon startup.