

Release Note

Version Info:

1. **Firmware Version:** 1.20.14 Build 20260918 Rel.30886
2. **Applied Model:**
 - a) SG6428XHP(UN) v1.0
 - b) SG6428XHP(UN) v1.6
 - c) SG6428XHP(UN) v1.20
 - d) SG6428XHP(UN) v1.26
 - e) SG6428XHP(IN) v1.28
3. **Fully Adapted Omada Controller version:** V6.1.
4. **Fully Adapted Omada App version:** N/A.
5. For downloading any firmware version, please refer to [Omada Download Center](#). For more information about firmware version number and fully adapted controller version, please refer to [Announcement on the Change of Omada Product Firmware Version Numbers](#).

Bug Fixed

1. Fixed an issue where ERPS configurations became abnormal after firmware upgrade.
2. Fixed an issue where VoIP port configurations were lost after full configuration delivery.
3. Fixed an issue where DNS configuration modifications could cause device disconnection.

Additional Information

1. SHA-256:
2f2dea9e8e7659eedea455f93fb38bb6acc4733f1f184491a5e30aa9bed6d933
2. SHA-512:
83ef40c82aca81099066763c3d3411a7bcfe7212881fa0117e823b8076a94f8d59cf44b61c68e37ec2a88dc7833c54e8302aebf058379527aa3dc06cda06a502