

Release Note

Version Info:

1. **Firmware Version:** 2.4.10 Build 20260916 Rel.63334

2. **Applied Model:**

- a) ER605(UN) v2.0
- b) ER605(UN) v2.20
- c) ER605(UN) v2.26
- d) ER605(UN) v2.30
- e) ER605(UN) v2.36
- f) ER605(UN) v2.6
- g) ER605(IN) v2.28
- h) ER605(IN) v2.38
- i) ER605(IN) v2.8
- j) ER605(BR) v2.36

3. **Minimum FW Version for Update:**

- a) UN v2.0: 2.3.2 Build 20251029 Rel.12727
- b) UN v2.20: 2.3.2 Build 20251029 Rel.12727
- c) UN v2.26: 2.3.2 Build 20251029 Rel.12727
- d) UN v2.30: 2.3.2 Build 20251029 Rel.12727
- e) UN v2.36: 2.3.2 Build 20251029 Rel.12727
- f) UN v2.6: 2.3.2 Build 20251029 Rel.12727
- g) IN v2.28: 2.3.2 Build 20251029 Rel.12727
- h) IN v2.38: 2.3.2 Build 20251029 Rel.12727
- i) IN v2.8: 2.3.2 Build 20251029 Rel.12727
- j) BR v2.36: 2.3.2 Build 20251029 Rel.12727

4. **Fully Adapted Omada Controller version:** 6.3.0.

5. **Fully Adapted Omada App version:** N/A.

6. For downloading any firmware version, please refer to [Omada Download Center](#).

New Features

- 1. Added support for intelligent abnormal event detection.

Bug Fixed

- 1. Fixed an issue where the online detection feature did not work properly in certain scenarios.
- 2. Fixed an issue where IP conflict detection could cause abnormal behavior after a device reboot or firmware upgrade.

3. Fixed an issue where ARP scanning traffic continued on a VLAN after the feature was disabled.
4. Fixed an issue where SIP ALG could not be disabled in standalone mode after a firmware upgrade.