

Release Note

Important Notice:

This firmware upgrade is irreversible. Contact VIGI support if issues are encountered after the firmware upgrade.

Version Info:

1. **Firmware Version:** 3.4.0 Build 260910 Rel.7420n
2. **Applied Model:**
 - InSight S355(2.8mm)(UN) 1.0
 - InSight S355(2.8mm)(UN) 1.6
 - InSight S355(4mm)(UN) 1.0
 - InSight S355(4mm)(UN) 1.6
 - InSight S355(6mm)(UN) 1.0
 - InSight S355(6mm)(UN) 1.6
3. **Recommended VIGI APP Versions:**
 - iOS: 2.7.95 or above
 - Android: 2.7.100 or above
4. **Recommended VIGI VMS version:** VIGI VMS 1.8.96 or above
5. **Recommended VIGI PC Client version:** VIGI PC Client v2.1.37
6. **Minimum FW Version for Update:** 2.5.0 Build 250422 Rel.34550n

New Features:

1. Added support for management by Omada Fusion Pro Gateways.

Enhancements:

1. Improved system security.

Bug Fixed:

1. Fixed some known issues.