

Release Note

Version Info:

1. **Firmware Version:** 1.0.4 Build 20260909 Rel.1220
2. **Applied Model:**
 - a) S7500-32C(UN) v1.0
 - b) S7500-32C(UN) v1.6
3. **Fully Adapted Omada Controller version:** V6.2.14 (Partial features supported).
4. **Fully Adapted Omada App version:** N/A.
5. For downloading any firmware version, please refer to [Omada Download Center](#). For more information about firmware version number and fully adapted controller version, please refer to [Announcement on the Change of Omada Product Firmware Version Numbers](#).

Bug Fixed

1. Fixed an issue where devices upgraded from non-ECSP V4 firmware to ECSP V4 firmware could fail to be adopted due to incorrect site account credentials after the site username or password had been changed.
2. Fixed an issue where ERPS configurations became abnormal after firmware upgrade.

Additional Information

1. SHA-256 Value:
f10083165e6b55392458b623d02b0573850f73cdb6904bd99275b8aea820918b
2. SHA-512 Value:
74273b49f9daa63b07a460920e3189c71d52f3c04ea607359aa35c213534db993cfcd72343f61e7725cfc6b9ece2c5460eaa01e9bc2a5ab23448c59aad8f2891