Release Note

Version Info:

1. **Firmware Version:** 1.20.4 Build 20260915 Rel.28712
2. **Applied Model:**

   a) SG5428XMPP(UN) v1.0

   b) SG5428XMPP(UN) v1.6

   c) SG5428XMPP(UN) v1.20

   d) SG5428XMPP(UN) v1.26

   e) SG5428XMPP(IN) v1.28
3. **Fully Adapted Omada Controller version:** 6.0.0.

   Security-related enhancements require Omada Controller V6.2.14 or above to take effect.
4. **Fully Adapted Omada App version:** N/A.
5. For downloading any firmware version, please refer to Omada Download Center . For more information about firmware version number and fully adapted controller version, please refer to Announcement on the Change of Omada Product Firmware Version Numbers .

Bug Fixed

1. Fixed an issue where devices could fail to be automatically adopted after a firmware upgrade when the Site password had been changed on the Controller under specific scenarios.
2. Fixed a configuration compatibility issue between STP and ERPS.

Additional Information

1. SHA-256 Value:
   820f48f4503c2d1ae3b807d7966adbff498c01c8ccbc40cb14a067353d83e3f9
2. SHA-512 Value:
   93b3b60f36741cbcab18511683d2ae574eff845d1f24266011c078a3b883763510ec8419ed278d6a04a8b2963f113c7caeb9f0af0acb253a67958da2aab5213c