Release Note

Important Notice:
This firmware upgrade is irreversible. Contact support if issues are encountered after the firmware upgrade.

Version Info:

1. **Firmware Version:** 1.0.1 Build 20261113 Rel. 11882
2. **Applied Model:** AP9788 v1.0/v1.6
3. **Minimum FW Version for Update**: 1.0.0 Build 20261009 Rel. 09263
4. **Fully Adapted Omada Controller version:** 6.2.
5. **Fully Adapted Omada App version:** 5.3.
6. For downloading any firmware version, please refer to Omada Download Center.

Bug Fixed:

1. Fixed an issue where the Controller could not adopt the device in certain scenarios.