Release Note

Version Info:

1. **Firmware Version:** 1.20.15 Build 20261120 Rel.82581
2. **Applied Model:**

   a) SG6654X(UN) v1.0

   b) SG6654X(UN) v1.6

   c) SG6654X(UN) v1.20

   d) SG6654X(UN) v1.26
3. **Fully Adapted Omada Controller version:** 6.1.0.
4. **Fully Adapted Omada App version:** N/A.
5. For downloading any firmware version, please refer to Omada Download Center .

Bug Fixed

1. Fixed an issue where CPU utilization remained abnormally high under certain scenarios.
2. Fixed an issue where the number of available mirror ports was limited when the switch operated in stack mode.
3. Fixed an issue where 802.1X authentication could fail under certain scenarios.

Additional Information

1. SHA-256 Value:
   366665b462ed30b5d62eb3e97b7a6e47a744bd552a7dc7356f26efca124ccb76
2. SHA-512 Value:
   cd599c9ae9ed875e41e43ceaca1038e8266a5c414c4c03716bcffe624f69e4a2914d92514260d5259228b380555368fbb25faee5b0012e563ed20bc4ce2fd9e2