

## **Recommended Controller Software Version: Omada Controller v3.2.6 or above**

### **Bug Fixed:**

Fixed the bug that enabling and configuring Port VLAN makes the wireless clients that connected to default SSID cannot communicate normally.

### **Notes:**

1. For EAP115-Wall v1 only.
2. Your device's configuration won't be lost after upgrading.
3. This version of firmware is applied to Omada APP of version 2.1.X or above.
4. You cannot downgrade if you upgrade from the firmware released in 2018 or earlier to this version directly.