

Recommended Controller Software Version: Omada Controller v3.2.x or above

Bug Fixed:

1. Fixed the bug that EAP may disconnect from Omada Controller.
2. Fixed the bug that the time zone displayed on the web UI of Standalone mode may be different from the connected PC.
3. Support Channel Limit.

Notes:

1. For EAP225-Outdoor v1 only.
2. Your device's configuration won't be lost after upgrading.
3. This version of firmware is applied to Omada APP of version 2.1.X or above.