

## **Recommended Controller Software Version: Omada Controller v3.2.x or above**

### Bug Fixed:

1. Fixed the bug that EAP may disconnect from Omada Controller.
2. Fixed the bug that the time zone displayed on the web UI of Standalone mode may be different from the connected PC.

### Notes:

1. For EAP245 v3 only.
2. Your device's configuration won't be lost after upgrading.
3. This version of firmware is applied to Omada APP of version 2.1.X or above.
4. You cannot downgrade if you upgrade from 2018 or older firmware to this version directly.