Bundled Firmware:

EAP120_V1, EAP220_V1

EAP110_V1, EAP110_V2, EAP110_V4

EAP115_V1, EAP115_V2, EAP115_V4

EAP225_V1, EAP225_V2, EAP225_V3

EAP245_V1, EAP320_V1, EAP320_V2

EAP330_V1,EAP330_V2

EAP110-outdoor_V1,EAP110-outdoor_V3

EAP225-outdoor_V1

New Features/Improvements:

User Interface improvements

Bug Fixed:

- 1. Fix: COMODO security software will cause Initialization failure of the Omada Controller
- 2. Fix: Logo picture with transparent background will become black when uploaded in portal login page.

Notes:

- 1. To use Omada Controller 2.5.x added new features, you need to upgrade your EAP's firmware to the corresponding version.
- 2. Once upgraded to this version of Omada Controller, you will NOT able to downgrade to an earlier version.
- 3. Portal configuration will be lost after upgraded to Controller 2.5.X from 2.4.X or earlier version.