

### **Bundled Firmware:**

[EAP110\\_V1](#), [EAP110\\_V2](#) [EAP110\\_V4](#)

[EAP115\\_V1](#), [EAP115\\_V2](#) [EAP115\\_V4](#)

[EAP225\\_V1](#), [EAP225\\_V2](#) [EAP225\\_V3](#)

[EAP225-Outdoor\\_V1](#)

[EAP110-Outdoor\\_V1](#) [EAP110-Outdoor\\_V3](#)

[EAP245\\_V1](#) [EAP245\\_V3](#)

[EAP115-Wall\\_V1](#) ( [EAP115-Wall](#) is suitable for EU version Only.)

[EAP225-Wall\\_V2](#)

[EAP320\\_V1](#) [EAP320\\_V2](#)

[EAP330\\_V1](#) [EAP330\\_V2](#)

### **New Features/Improvements:**

- 1.Safety performance optimization.
- 2.Web UI optimization.
- 3.Optimized the format requirement and handling mechanism for Local User Account importing files.

### **Bug Fixed:**

- 1.Fixed the bug that clients may lose the authorized status in the next ten minutes, after passing the Facebook Portal authentication.
- 2.Fixed the bug that customer can add port number except for port 1024~65535, if customer has already added http/https prefix in the URL of Free Authentication Policy.
- 3.Fixed the bug that Controller will still adopt the EAP, after skipping the Select Devices process in the quick setup wizard of Omada Controller.

### **Notes:**

1. To use Omada Controller 2.6.x new features, you need to upgrade your EAP's firmware to the corresponding version.
2. Once upgraded to this version of Omada Controller, you will NOT able to downgrade to an earlier version.
3. Portal configuration will be lost after upgraded to Omada Controller 2.6.X from 2.4.X or earlier version.