

Recommended Controller Software Version: Omada Controller v4.1.5 or above

New Feature/Enhancement:

1. Solve the problem of low 5G power value in the factory state.

Notes:

1. For EAP615-Wall v1 only.
2. This version of firmware is applied to the Omada APP of version 3.0.X or above.
3. This firmware is only compatible with Omada controller v4.1.5 or above. If you are using the old Omada controller and need to manage EAP615-Wall, you must upgrade the Omada controller to version 4.1.5 or above. You can follow [Omada Controller Upgrade Guide](#) to upgrade omada controller.