

Recommended Controller Software Version: Omada Controller v4.1.5 or above

New Feature/Enhancement:

1. Fully adapt to Omada SDN controller V5.x
2. Add the feature that when using Migration moving EAP to an invalid IP address of Omada Controller, the EAP will roll back.
3. Optimize security vulnerabilities.

Bug fixed:

1. Fixed the bug that the LED light is still on after using Locate function.
2. Fixed the bug that the 2.4G clients sometimes cannot access the internet when the EAP gets the MAC authentication configuration from the Omada Controller.
2. Fixed the bug that the EAP will automatically restart when using with some wireless devices.
3. Fixed the FragAttacks vulnerabilities.

Notes:

1. For EAP245 v3 only.
2. This version of firmware is applied to the Omada APP of version 3.0.X or above.
3. **This firmware is only compatible with Omada controller v4.1.5 or above. If you are using the old Omada controller and need to manage EAP615-Wall, you must upgrade the Omada controller to version 4.1.5 or above. You can follow [Omada Controller Upgrade Guide to upgrade omada controller.](#)**