

## Recommended Controller Software Version: Omada Controller v4.1.5 or above

### New Feature/Enhancement:

1. Fully adapt to Omada SDN controller V5.x.
2. Add Mesh function.
3. Optimize security vulnerabilities.

### Bug fixed:

1. Fixed the bug that the LED light is still on after using Locate function.
2. Fixed the bug that the 2.4G clients sometimes cannot access the internet when the EAP gets the MAC authentication configuration from the Omada Controller.
3. Fixed the bug that when setting 80 MHz channel width for 5G SSID, the wireless mode will turn to 802.11ac in Controller mode.
4. Fixed the bug that some clients cannot connect to the SSID when the encryption mode is WPA-PSK.

### Notes:

1. For EAP620 HD v1 only.
2. This version of firmware is applied to the Omada APP of version 3.0.X or above.
3. This firmware is only compatible with Omada controller v4.1.5 or above. If you are using the old Omada controller and need to manage EAP615-Wall, you must upgrade the Omada controller to version 4.1.5 or above. You can follow [Omada Controller Upgrade Guide](#) to upgrade omada controller.