

This firmware fully adapts the Omada SDN platform but only compatible with Omada Controller v4.3.5 or above.

If you are using an old Omada controller and plan to upgrade this firmware for EAP, you must upgrade the Omada Controller as well: [Upgrade Guide](#)

Bug fixed:

1. Fixed the bug that Tx power in 5G is lower than the value set.
2. Fixed the bug that sometimes the packets drop rate is high.

Notes

1. For EAP670 v1 only.
2. This version of firmware is applied to the Omada APP of version 3.2.3x or above.