
TP-Link FW Release Notes

Product Name	EC230-G1(PLWISP) 1.0	
Firmware Version	2.0.0 0.9 v6034.0 Build 210924 Rel.31505n	
Release Date	Nov. 8, 2021	
Release purposes:		
Software iteration		
Change items (Include New features, feature changes, bug fix)		
No.	Description	Note
1	Fixed soft acceleration sometimes having a low speed.	
2	Optimized the policy for deleting ARP entries and avoiding hash conflicts in ARP/NAPT entries.	
3	Fixed the color of the wireless icon on the basic page is incorrect.	
4	Fixed issue that speed from 800Mbps drops to 250Mbps.	
5	Fixed LAN MAC leak when enable multi WAN MACVLAN function.	
6	Fixed the static prefix of LAN cannot be set.	
7	Fixed possible issue with rapid channel switching	
8	Fixed issue that If the RA is not sent in PPPoE session, LAN PC cannot reach IPv6 Internet.	