

Recommended Controller Software Version: Omada Controller v5.5 or above

Bug fixed:

1. Fix the EAP is still in cloud after disabling Allow Data Collection.
2. Fix the EAP automatically enables Allow Data Collection in Standalone mode.
3. Improve stability of the hardware.
4. Enable watchdog in hardware.

Notes:

1. This version of firmware is applied to the Omada APP v3.0.X or above.
2. **This firmware is fully adapted to Omada SDN Controller v5.5 or above. You can follow [Omada Controller Upgrade Guide](#) to upgrade Omada Controller.**