

**Recommended Controller Software Version: Omada Controller v5.9 or above**

Bug fixed:

1. Fixed the issue that the portal page could not pop up when used with HTTPS.
2. Fixed the issue that the portal page of the clients had completed portal authentication in the 6G band did not pop up when connecting to a newly adopted EAP.

Notes:

1. This version of firmware is applied to the Omada APP v4.10 or above.