

**Bug Fixes:**

1. Fixed a bug that caused the InSight S345-4G camera to fail remote upgrades when XLAT (IPv4/IPv6 Translation) was enabled.