

## **Version info**

**Firmware for SG3428MP(UN) 6.20 and 6.26. This firmware is fully adapted to Omada Controller V5.15.**

### Enhancements

1. Optimize the identification for IPC machines.
2. Optimize the processing when Port Description containing special characters.
3. Optimize the logs of VLAN creation in special cases.

### Bug fixed

1. Fixed a problem that the MVR VLAN cannot be switched in some scenarios.
2. Fixed a compatibility issue with Multicast Route Unknown.
3. Fixed a problem of incorrect statistics of packets received in some scenarios.
4. Fixed a problem with 10 Gigabit optical modules identification in some scenarios.