

Version Info:

Firmware for SG3428XMPP(UN) 1.0/1.6 (IN)1.8. This firmware is fully adapted to Omada Controller V5.15

Enhancements

- 1, Optimize the identification for IPC machines.
- 2, Optimize the processing when Port Description containing special characters.
- 3, Optimize the logs of VLAN creation in special cases.

Bug fixed

- 1, Fixed a problem that the MVR VLAN cannot be switched in some scenarios.
- 2, Fixed a compatibility issue with Multicast Route Unknown.
- 3, Fixed a problem of incorrect statistics of packets received in some scenarios.
- 4, Fixed a problem with 10 Gigabit optical modules identification in some scenarios.