

Version info

Firmware for TL-SG3428MP(UN) 3.0. This firmware is fully adapted to Omada Controller V5.15.

Enhancements

1. Optimize the identification for IPC machines.
2. Optimize the processing when Port Description containing special characters.
3. Optimize the logs of VLAN creation in special cases.

Bug fixed

1. Fixed a problem that the MVR VLAN cannot be switched in some scenarios.
2. Fixed a compatibility issue with Multicast Route Unknown.
3. Fixed a problem of incorrect statistics of packets received in some scenarios.
4. Fixed a problem with 10 Gigabit optical modules identification in some scenarios.