

## **Recommended Controller Software Version: Omada Controller v5.14 or above**

### Bug Fixed:

1. Fixed the issue that wireless clients may not be able to connect with the PPSK without Radius SSID.
2. Fixed the issue where the AP could not disconnect the mesh link after being wired to the network.
3. Fixed the issue that wireless clients cannot pop up the portal authentication page automatically during the connection process in some scenarios.
4. Fixed the issue where wireless clients take longer to automatically pop up the portal authentication page in an external network environment with IPv6.
5. Fixed some issues about abnormal portal authentication on wireless clients with https redirection enabled
6. Fixed the issue of inaccurate traffic statistics in mesh scenarios.
7. Fixed the issue of URL Pre-Authentication Access not working on mesh APs.
8. Fixed the issue of DFS not working properly as expected.
9. Fixed the issue of wireless performance degradation when the ETH1 port is disabled.

### Notes:

1. This version of firmware is applied to the Omada APP v4.20 or above.