

## Version info

Firmware for S6500-48GP6XF(UN) 1.0. This firmware is fully adapted to Omada Pro Controller V1.10.20.

### SHA-256 Value:

A9AFCB7DDCA30053C0508D06663C79844A2CB2081C807CFD1F50DAB1A3CDEA8B

### SHA-512 Value:

B40C699D2DE45447181F13D6028C9E1A62A9FAEF9C21AE9ACF8D48F65A9C6DEB4AE234C67DE4C65CEEB07104794E26732A8E8C1BC27813BDF42D05D1BF816714

## New features

1. Add support for controller adoption through M-LAG member ports.
2. Add support for DAD-v6 in M-LAG.

## Enhancements

1. Enhanced stability of stack.
2. Improve fault recovery performance in M-LAG.

## Bug fixed

1. Fixed the issue where static IP occasionally be lost after upgrade in controller mode.
2. Fixed the issue where ports fail to link up occasionally after upgrade in controller mode.
3. Fixed the issue where ports fail to link up occasionally under stress testing.
4. Fixed the issue of kernel hang occurring occasionally under stress testing.