

**Recommended Controller Software Version: Omada Controller Pro v1.9 or above**

Enhancements:

1. Enhanced stability.

Bug fixed:

1. Fixed the issue of mesh AP disconnection when OFDMA is enabled. As UL\_OFDMA is not allowed in STA mode, it has been disabled.

Notes:

1. This version of firmware is applied to the Omada APP v4.18 or above.