Version Info:

This firmware is fully adapted to Omada Controller v5.15.24. Minimum FW Version for Update: 1.3.1 Build 20240828 Rel. 83546, for downloading of any firmware version, please refer to <u>Omada Download Center</u>.

Enhancements:

1. Optimized the CPU utilization.

Bug fixed:

1. Fixed the issue that will interrupt IPC's video stream on 2.4GHz randomly.

Notes:

1. This version of firmware is applied to the Omada APP v4.24 or above.