

Recommended Controller Software Version: Omada Controller v5.15.24 or above.
Minimum FW Version for Update: 1.3.0 Build 20240828 Rel. 83857 and above, for downloading of any firmware version, please refer to [Omada Download Center](#).

Enhancements:

1. Optimized the CPU utilization.

Bug fixed:

1. Fixed the issue that will interrupt IPC's video stream on 2.4GHz randomly.

Notes:

1. This version of firmware is applied to the Omada APP v4.24 or above