

Version Info:

This firmware is fully adapted to Omada Controller v5.15.24.

Minimum FW Version for Update: 1.5.1 Build 20241102 Rel. 63319, for downloading of any firmware version, please refer to [Omada Download Center](#).

New features:

1. Added support for Radius portal logout and CHAP encryption in Standalone mode.
2. Added support for portal landing page selection in Standalone mode.
3. Added support for modifying the Inform URL via SSH.
4. Added EAP Power Supply information in LLDP messages.

Enhancements:

1. Optimized the default NTP Server list.
2. Optimized EAP Portal authentication functionality.
3. Optimized the configuration logic to reduce the configuration time for some settings.
4. Optimized the peak performance.

Bug fixed:

1. Fixed the issue that will cause the EAP to print incorrect logs while clients are roaming.

Notes:

1. This version of firmware is applied to the Omada APP v4.24 or above.