

## Version Info:

**Firmware for S7500-24Y4C(UN) 1.0. This firmware is fully adapted to Omada Pro Controller V1.10.20**

**SHA256:b4512d8b442d75be58206f1995dd99497c3d5b4bed65020cddd56df7ffda46db**

**SHA512:788401b9e19ab6a768d4bd84182ccea63f8e3a13d791c56aa86de63c7a9b3636429fdaadcfe772ffe3d157a29e568a07167f6cab0b8a9d9273c6e482b241d10**

## Enhancements

1. Optimized internal communication mechanism for stacking to improve stability.
2. Enhanced MLAG stability.
3. Improved MAC address migration stability in M-LAG scenarios.

## Bug fixed

1. Fixed the issue where IP addresses could not be obtained from the DHCP server in MLAG scenarios.
2. Fixed the issue where Layer 3 traffic could not quickly recover after interruption in MLAG scenarios.
3. Fixed the abnormal synchronization of full-capacity FDB entries in MLAG scenarios.