

Version Info:

Firmware for S7500-26XF6Y(UN) 1.0. This firmware is fully adapted to Omada Pro Controller V1.10.20

SHA256:b4512d8b442d75be58206f1995dd99497c3d5b4bed65020cddd56df7ffda46db

SHA512:788401b9e19ab6a768d4bd84182ccea63f8e3a13d791c56aa86de63c7a9b3636429fdaadcfe772ffe3d157a29e568a07167f6cab0b8a9d9273c6e482b241d10

Enhancements

1. Optimized internal communication mechanism for stacking to improve stability.
2. Enhanced MLAG stability.
3. Improved MAC address migration stability in MLAG scenarios.

Bug fixed

1. Fixed the issue where IP addresses could not be obtained from the DHCP server in MLAG scenarios.
2. Fixed the issue where Layer 3 traffic could not quickly recover after interruption in MLAG scenarios.
3. Fixed the abnormal synchronization of full-capacity FDB entries in MLAG scenarios.