

Version Info:

1. Minimum FW Version for Update: 2.0.0 Build 20180601 Rel. 52885.
2. After upgrading this firmware, rolling back to any of the previous version is forbidden.
3. This firmware is fully adapted to Omada Controller v5.9.
4. For downloading of any firmware version, please refer to [Omada Download Center](#).

New features:

1. Added support for cluster mode.

Enhancements:

1. Optimized the CPU utilization.
2. Enhanced network security.
3. Optimized EAP Portal authentication functionality.

Notes:

1. This version of firmware is applied to the Omada APP v4.10 or above.