

## Release Note for G36W-4G(US) v1.0/v1.6

### Important Notice:

This is a transitional firmware for RED certification compliance which is not complied to RED certification, to fully comply to RED certification, it is recommended to upgrade to version 1.1.8 afterwards.

This firmware upgrade is irreversible. Contact Omada technical support if downgrade is required.

### Version Info:

#### 1. Applied Model:

- a) G36W-4G (US) v1.0
- b) G36W-4G (US) v1.6

#### 2. Firmware Version: 1.1.7 Build 20250901 Rel.76815

#### 3. Minimum FW Version for Update:

- a) US v1.0: 1.0.3 Build 20240207 Rel.50108
- b) US v1.6: 1.0.3 Build 20240207 Rel.50108

For downloading of any firmware version, please refer to [Omada Download Center](#).

#### 4. Recommended Controller Version: Omada Pro Controller v1.9

#### 5. Recommended APP Version: No

### New Features:

No.

### Enhancements:

No.

---

**Bug Fixed:**

1. Fixed the issue that devices did not report Permanent ARP entries to the Controller.
2. Fixed several feedback issues.
3. Fixed several security vulnerabilities.

**Additional Information:**

1. Enhanced device security.