

Version Info:

1. Minimum FW Version for Update: 1.0.2 Build 20250620 Rel. 41334.
2. This firmware upgrade is irreversible. Contact Omada technical support if downgrade is required.
3. Recommended Omada Controller version 5.15 or above.
4. For downloading of any firmware version, please refer to [Omada Download Center](#).

Enhancements:

1. Enhanced overall security.

Bug fixed:

1. Fixed an issue where clients could not connect to 6G-related MLO networks in certain cases.
2. Fixed an issue where the Site Inform URL could not be configured on the device's Standalone page.

Notes:

1. This version of firmware is applied to the Omada APP 4.24 or above.