

Release Note for ER605(UN) v1.0/v1.60

Important Notice:

This firmware resolves several security vulnerabilities.

Version Info:

1. Applied Models:

- a) ER605(UN) v1.0
- b) ER605(UN) v1.60
- c) TL-R605(UN) v1.0
- d) TL-R605(UN) v1.60

2. Firmware Version: 1.3.2 Build 20251030 Rel.16640

3. Minimum FW Version for Update:

- a) ER605(UN) v1.0: 1.0.0 Build 20200930 Rel.36519 and above
- b) ER605(UN) v1.60: 1.0.0 Build 20200930 Rel.36519 and above
- c) TL-R605(UN) v1.0: 1.0.0 Build 20200930 Rel.36519 and above
- d) TL-R605(UN) v1.60: 1.0.0 Build 20200930 Rel.36519 and above

For downloading of any firmware version, please refer to [Omada Download Center](#).

4. Recommended Controller Version: 5.8 and above

5. Recommended APP Version: No

New Features:

No.

Enhancements:

No.

Bug Fixed:

1. Fixed several security issues.

Additional Information:

No.